




TACH CABLE

Disconnect the tach cable from the tach pick-up at the base of the distributor. Insert the adapter into the pick-up and hand tighten the free-floating nut. Attach and tighten the tach cable to the threaded fitting in the adapter. Lubricate the grease fitting periodically. NOTE: It may be necessary to rotate the distributor and retune the engine to insert the adapter and clear the firewall.

SPEEDOMETER CABLE

Attach the adapter to the transmission and speedometer cable to the adapter. Tighten securely and lubricate well. Grease will be injected into the speedometer cable housing preventing most speedometer cable problems.

IT'S THAT EASY! NO MORE TACH CABLE PROBLEMS!



PART NO. 272110

SHEET 1 OF 1

DATE	REVISION	AUTH	DR
07/07/05			

INSTALLATION INSTRUCTIONS

PART NO. 272110

SHEET 1 OF 1

